

## M.O.T. PASSES AND FAILURES

REGISTRATION NUMBER	MAKE/MODEL	OPERATOR	YEAR OF 1ST REGISTRATION	6 MONTHLY TEST	ANNUAL TEST	PASS	FAIL	DATE	MILEAGE	LIC.NO.
X676 MOB	FORD MONDEO	BACUP TAXIS	2000	Y			Y	08/12/2005	132,411	HC 57
X789 SOC	TOYOTA AVENSIS	RED BARON	2000	Y			Y	13/12/2005	102,263	HC 115
T558 ABW	FORD MONDEO	ARROW TAXIS	1999		Y		Y	16/12/2005	188,569	HC 18
R644 EYS	FORD TRANSIT	BACUP TAXIS	1997	Y			Y	04/01/2006	217,793	HC 49
W984 MDB	FORD MONDEO	BACUP TAXIS	2000	Y			Y	04/01/2006	114,732	
MK52 TOU	SEAT ALHAMBRA	BACUP TAXIS	2002	Y			Y	05/01/2006	60,273	
X61 OUB	FORD MONDEO	G B TAXIS	2000	Y			Y	19/01/2006	91,425	HC 129
T995 JBF	VAUXHALL ASTRA	ARROW TAXIS	1999	Y			Y	20/01/2006	147,984	HC 91
R644 EYS	FORD TRANSIT	BACUP TAXIS	1997	Y			Y	24/01/2006	218,220	HC 49
Y217 KAV	TOYOTA AVENSIS	OWNER DRIVER	2001	Y			Y	10/11/2005	113,207	HC 110
S629 EUB	FORD TRANSIT	ROYAL TAXIS	1998	Y			Y	25/11/2005	175,391	HC 92
P258 NSJ	LDV CONVOY	ROSSENDALE TAXIS	1996		Y		Y	22/11/2005	153,754	
W93 LMS	TOYOTA AVENSIS	A1/INTIME	2000		Y		Y	10/02/2006	123,472	
V528 VWL	ROVER 400	G B TAXIS	1999	Y			Y	06/10/2005	95,163	
W713 LMS	TOYOTA AVENSIS	RED BARON	2000	Y			Y	05/10/2005	65,221	
V156 GJB	TOYOTA AVENSIS	A1/INTIME	1999	Y			Y	08/02/2006	223,369	HC 28
W213 YFR	VAUXHALL ASTRA	RED BARON	2000	Y			Y	31/01/2006	111,479	
DV52 EEA	VAUXHALL VECTRA	AIRWOLF TAXIS	2002	Y			Y	31/01/2006	68,971	
DV52 EEA	VAUXHALL VECTRA	AIRWOLF TAXIS	2002	Y			Y	01/02/2006	69,045	

# VT30 Refusal of an MOT Test Certificate

(IMPORTANT: Read notes overleaf)

# VOSA

Vehicle & Operator Services Agency

MOT test number  
244467036037

Make  
FORD

Odometer reading  
147441 Miles

Registration mark  
X654REO

Model  
MONDEO

Test class  
IV

Vehicle identification or chassis number  
WFOAXXGBBAYD79984

Colour  
SILVER

Approximate year of first use  
2001

Design gross weight (GV)  
N/A kg

**A**

### Tested Items that failed

- 001 Nearside headlamp aim too low [1.6.D2]
- 002 Nearside registration plate lamp not working [1.1.5c]
- 003 Offside stop lamp not working [1.3.2a]
- 004 Nearside front direction indicator not in good working order (not working) [1.5.A1b]
- 005 Nearside rear rear position lamp(s) not in good working order (not working) [1.1.4a]
- 006 Offside front coil spring fractured [2.4.C.1a]
- 007 Nearside front tyre tread depth below requirements of 1.6mm [4.1.D.1]
- 008 Offside front tyre tread depth below requirements of 1.6mm [4.1.D.1]
- 009 Offside front anti-roll bar has excessive play in a ball joint [2.4.G.3]

*o/s/r lower arm*

page 1

**B**

I certify that for the reason(s) shown in A above the vehicle was not shown to comply with the statutory requirements.

Issuer's name in CAPITALS  
N. DOWNHAM

Signature of Issuer

*6 months Test.*  


Date / Time

FEBRUARY 6th 2006  
12:29

Test station number

42406

**C**

Warning: In my opinion, the vehicle is dangerous to drive because of the following defects listed in A above

N/A

Inspection Authority

J A TAYLOR CAR SALES  
BURY ROAD  
RAWTENSTALL  
ROSSENDALE  
BB4 6HL



# VT30 Refusal of an MOT Test Certificate

(IMPORTANT: Read notes overleaf)



Vehicle & Operator Services Agency

MOT test number	Make	Odometer reading
113139736086	TOYOTA	223369 Miles
Registration mark	Model	Test class
V156GJB	AVENSIS	IV
Vehicle identification or chassis number	Colour	Approximate year of first use
SB164ABN10E086250	BLUE	1999
Design gross weight (GV)		
N/A kg		

A

### Measurements

Brakes Failures: RBT Park Brake Efficiency: 9%, RBT Front Brake Imbalance: 27%

### Tested Items that failed

- 001 Nearside front front position lamp(s) not in good working order (not working) [1.1.4a]
- 002 Offside front front position lamp(s) not in good working order (not working) [1.1.4a]
- 003 Nearside registration plate lamp not working [1.1.5c]
- 004 Nearside brake pad less than 1.5 mm thick [3.5.1f]
- 005 Offside front brake pad less than 1.5 mm thick [3.5.1f]
- 006 Nearside brake cable has restricted free movement [3.5.1j]
- 007 Offside brake cable has restricted free movement [3.5.1j]
- 009 Parking brake efficiency below requirements [3.7.A.9/10]
- 010 Brakes imbalanced [3.7.A.2e]

page 1

*6 monthly Failure HLC 28*

VT32 Issued....

B

I certify that for the reason(s) shown in A above the vehicle was not shown to comply with the statutory requirements.

Issuer's name in CAPITALS

Signature of Issuer

N. DOWNHAM

Date / Time

FEBRUARY 8th 2006  
10:09

Test station number

42406


C

Warning: In my opinion, the vehicle is dangerous to drive because of the following defects listed in A above

Inspection Authority

N/A

J A TAYLOR CAR SALES  
BURY ROAD  
RAWTENSTALL  
ROSSENDALE  
BB4 6HL



# VT30 Refusal of an MOT Test Certificate

(IMPORTANT: Read notes overleaf)



Vehicle & Operator Services

MOT test number 441981336089	Make VAUXHALL	Odometer reading 111479 Miles
Registration mark W213YFR	Model ASTRA	Test class IV
Vehicle identification or chassis number WOL0TGF35Y8145232	Colour WHITE	Approximate year of first 2000
Design gross weight (GV) N/A	kg	

A

### Tested Items that failed

- 001 Nearside windscreen wiper blade deteriorated [8.2.2]
- 002 Offside windscreen wiper blade deteriorated [8.2.2]
- 003 Offside track rod end ball joint has excessive play [2.2.B.1f]

VT30 Tested

B

I certify that for the reason(s) shown in A above the vehicle was not shown to comply with the statutory requirements

Issuer's name in CAPITALS

Signature of Issuer

N DOWNHAM

Date / Time

31.01.06

14:22

Test station number

42401

C

Warning: In my opinion, the vehicle is dangerous to drive because of the following defects listed in A above

Inspection Authority

N/A

J A TAYLOR CAR SALES  
BURY ROAD  
RAWTENSTALL  
ROSSENDALE  
BB4 6HL

\* 6 monthly Vehicle Inspection

Please keep this failure notice and produce it at the Testing Station in the event of a re-examination. SBS

# VT30 Refusal of an MOT Test Certificate

(IMPORTANT: Read notes overleaf)



Vehicle & Operator Service

MOT test number  
540811236048

Make  
VAUXHALL

Odometer reading  
68971 Miles

Registration mark  
DV52EEA

Model  
VECTRA LS DTI 16V

Test class  
IV

Vehicle identification or chassis number  
W0L0ZCF6838017917

Colour  
GREY

Approximate year of first registration  
2002

Design gross weight (GV)  
N/A kg

A

### Tested Items that failed

- 001 Nearside headlamp aim too high (hotspot upper edge above the horizontal 0% [1.6.D1])
- 002 Nearside ball joint has excessive play [2.2.B.1f]

page 1

VT32 Issued....

B I certify that for the reason(s) shown in A above the vehicle was not shown to comply with the statutory requirements

Issuer's name in CAPITALS  
N. DOWNHAM

Signature of issuer

Date / Time  
JANUARY 31st 2006  
12:50

Test station number  
42406

C Warning: In my opinion, the vehicle is dangerous to drive because of the following defects listed in A above

N/A

Inspection Authority

J A TAYLOR CAR SALES  
BURY ROAD  
RAWTENSTALL  
ROSSENDALE  
BB4 6HL



\* Monthly Examination

Please keep this failure notice and produce it at the Testing Station in the event of a re-examination.

# VT30 Refusal of an MOT Test Certificate

(IMPORTANT: Read notes overleaf)



Vehicle & Operator Service

MOT test number

400092236093

Make

VAUXHALL

Odometer reading

69045 Miles

Registration mark

DV52EEA

Model

VECTRA LS DTI 16V

Test class

IV

Vehicle identification or chassis number

W0L0ZCF6838017917

Colour

GREY

Approximate year of first registration

2002

Design gross weight (GV)

N/A kg

A

## Tested Items that failed

001 Nearside ball joint has excessive play [2.2.B.1f]

page 1

B

I certify that for the reason(s) shown in A above the vehicle was not shown to comply with the statutory requirements.  
Issuer's name in CAPITALS

Signature of issuer

N. DOWNHAM

Date / Time

FEBRUARY 1st 2006  
14:23

Test station number

42406

C

Warning: In my opinion, the vehicle is dangerous to drive because of the following defects listed in A above

Inspection Authority

N/A

J A TAYLOR CAR SALES  
BURY ROAD  
RAWTENSTALL  
ROSSENDALE  
BB4 6HL

x 6 months examination

Please keep this failure notice and produce it at the Testing Station in the event of a re-examination.

# VT30 Refusal of an MOT Test Certificate

(IMPORTANT: Read notes overleaf)



Vehicle & Operator Services Agency

MOT test number	Make	<i>id/c 130 6 months</i>	Odometer reading
844408956099	TOYOTA		98754 Miles
Registration mark	Model		Test class
X865VFG	AVENSIS		IV
Vehicle identification or chassis number	Colour		Approximate year of first use
SB153ZBN10E005715	SILVER		2000
Design gross weight (GV)			
N/A kg			

### Tested Items that failed

001 Nearside rear tyre tread depth below requirements of 1.6mm [4.1.D.1]

page 1

VT32 Issued.

**B** I certify that for the reason(s) shown in A above the vehicle was not shown to comply with the statutory requirements.  
Issuer's name in CAPITALS

Signature of Issuer

N. DOWNHAM

Date / Time FEBRUARY 27th 2006  
14:26

Test station number 42406

**C** Warning: In my opinion, the vehicle is dangerous to drive because of the following defects listed in A above

Inspection Authority

N/A

J A TAYLOR CAR SALES  
BURY ROAD  
RAWTENSTALL  
ROSSENDALE  
BB4 6HL